

2012 FIRE RELATED VEHICLE RECALLS

AUDI

A3 2.0 TDI DIESEL ENGINE--LEAKING #2 INJECTOR.

R8 FUEL LINE RUBBING ON HEAT SHIELD.

BMW

6 SERIES OVERHEATED WATER PUMP CIRCUIT BOARD (V8 OR V12 ONLY).

7 SERIES OVERHEATED WATER PUMP CIRCUIT BOARD (V8 OR V12 ONLY).

X5 DEFECTIVE POWER STEERING GEAR CAN SPRAY LEAKING FLUID ONTO THE EXHAUST.

X5 SAV OVERHEATED WATER PUMP CIRCUIT BOARD (V8 OR V12 ONLY).

X6 SAV OVERHEATED WATER PUMP CIRCUIT BOARD (V8 OR V12 ONLY).

CHEVROLET

CAPTIVA SPORT OVERHEATED POWER STEERING RESERVOIR MAY LEAK FLUID.

CRUZE SPILLED OR DRIPPING OIL COLLECTING ON ENGINE
HEAT SHIELD.

CRUZE FUEL LEAKING DURING A COLLISION MAY IGNITE.

IMPALA MISROUTED POWER STEERING LINES MAY
CONTACT THE CATALYTIC CONVERTER.

INFINITY

M LEAKING FUEL PRESSURE SENSOR.

QX LEAKING FUEL PRESSURE SENSOR.

JEEP

COMPASS LEAKING FUEL DURING IMPACT OR ROLL-OVER.

PATRIOT LEAKING FUEL DURING IMPACT OR ROLL-OVER.

NISSAN

JUKE LEAKING FUEL PRESSURE SENSOR.

VOLKSWAGEN

GOLF 2.0 TDI DIESEL ENGINE -- LEAKING #2 INJECTOR.

JETTA 2.0. TDI DIESEL ENGINE -- LEAKING #2 INJECTOR.

PASSAT

LEAKING DIESEL FUEL FILTER.

VOLVO

S60

LEAKING FUEL LINE QUICK CONNECTOR.

S60

UNDER BODY COATING DAMAGING FUEL LINES
CAUSING A LEAK.